



Sun Path Products Inc. 404 W Edinborough Ave. Raeford, NC 28376 (910) 875-9002

TSO LABEL ERROR

March 13, 2014

On March 13, 2014 Sun Path Products discovered that there was a typographical error on TSO labels on our harness/container systems manufactured between October 2013 and March 2014. The TSO Label should state:


APPROVED UNDER TSO-C23d AND QAC (I) 121. THIS HARNESS/CONTAINER SYSTEM IS LIMITED FOR USE BY FULLY EQUIPPED PERSONS UP TO 300LB (136KG) AND UP TO 170 KNOTS AVERAGE TEST PEAK FORCE MEASURED: 7629.5 LBS.

The original TSO wording as stated above is applicable to the harness/containers that are affected by the error.

Sun Path Products has authorized the original owner to make the following modification:

1. LOCATE THE TSO LABEL ON YOUR JAVELIN HARNESS CONTAINER SYSTEM AND VERIFY 170 KNOTS.

INCORRECT



2. USE A FINE POINT MARKER AND DRAW A SINGLE LINE THROUGH 107 AND WRITE 170 IN ONE OF THE TWO WAYS PICTURED BELOW.

HORIZONTAL



VERTICAL

